



REFERENCE	BT_2010_FR20_01
DATE	12 th February 2010
SUBJECT	Oil level
PART	Oil tank

Oil tank conformity

Following a production problem, the oil tank delivered so far on the New Formula Renault 2.0 represents a risk for the engine in some specific conditions.

We have experienced important oil loss from the oil tank to the catch tank on anti clockwise circuit with high speed corners (left corners) such as Motorland.

Therefore the engine oil level and the catch tank level must be checked every run. If the catch tank level increases regularly, shorten the run length and increase the periodicity of the oil level check.

Renault Sport will come with a proper solution within the next few days.





RENAULT *SPORT*

FORMULA
RENAULT **2.0**

