



REFERENCE	BT_2012_FR20_2_UK
DATE	21st March, 2012
SUBJECT	New o-ring for Gearbox secondary shaft
PART	Gearbox housing

1. Gearbox secondary shaft new o-ring

SADEV and Renault Sport have noticed that in certain conditions, the new o-ring ref. 01 00 202 061 can get damaged really quickly.

Therefore, it is allowed to continue using the original o-ring ref. 01 00 201 222 as well.

The original o-ring fulfils its function for 2,000/2,500km maximum and then requires replacement.

We invite you to check the state of your o-ring as soon as possible to prevent the sleeve from wearing too much if the o-ring is damaged or deformed.

Renault Sport and Sadev are already working on a further improvement and will come back to you as soon as a new solution is validated and available.

