

RENAULT SPORT



Technical Bulletin N°10

REFERENCE	BT_2013_FR20_10_UK
DATE	3rd of April, 2013
SUBJECT	Master cylinder reservoir's extension
PART	Brake system

1. Master cylinder reservoir's extension

Some of you have encountered issues to bleed correctly the brake lines while using the new master cylinder reservoirs' extension.

The problem is still under investigation and Renault Sport has decided to allow removing the extension system while the problem is not understood and solved.

Therefore, it is allowed from now to mount the reservoirs on top of all 3 master cylinders.

Renault Sport will come back to you as soon as the problem is clarified.



